

Recommended position of chocks for the
ASTender 400
330
826
1900
153.11°
121.83°